

REPORT OF CHANNEL CONDITIONS 100 TO 400 FEET WIDE <i>(EP 1130-2-520)</i>						PAGE 1 OF 1	
						DATE 29 August 2008	
TO: Navigation Interests				FROM: U.S. Army Engineer District, Baltimore P.O. Box 1715 Baltimore, Maryland 21203-1715			
RIVER/HARBOR NAME AND STATE Potomac River below Washington D.C. Maryland					MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD		
NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER <i>(feet)</i>	MIDDLE HALF <i>(feet)</i>	RIGHT OUTSIDE QUARTER <i>(feet)</i>
		WIDTH <i>(feet)</i>	LENGTH <i>(miles)</i>	DEPTH <i>(feet)</i>			
Marshall Hall Bar Sta. 0+000 to 10+289 Surveyed on 14 August 2008		200	2	24	23	24	24
REMARKS <i>(Continue on reverse)</i> All depths refer to MLLW for the 1960-1978 tidal epoch. This information represents the results of surveys made on the dates indicated and can only be as indicating the general results at that time. Length of channel is reported to the nearest mile. Actual length of channel is 1.95 miles. Depths are reported to the nearest foot. LQ=E1281144.75, N372997.33 (23.1') MH=E1287522.79, N374714.92 (23.9') RQ=E1288117.05, E374812.34 (24.0')							